

Fig. 1




Fig.2





Fig.3






Fig.5

6/31




Fig. 6








Fig. 7








Fig. 11




Fig. 13




Fig. 14




Fig.15




Fig. 16A





Fig. 16B






Fig. 17




Fig. 18




Fig.19




Fig. 20

Fig. 21A

CIRCUIT A			
XMIT ID	RCV ID	COLLISION?	MONITOR RCVR?
1	1	No	Yes
0	0	No	No
0	0	No	No
•	•	•	•
•	•	•	•
•	•	•	•

Fig. 21B

CIRCUIT B			
XMIT ID	RCV ID	COLLISION?	MONITOR RCVR?
1	1	No	Yes
0	0	No	No
1	0	Yes	Yes
CIRCUIT B DECLARED A RECEIVER			




Fig. 22




Fig. 23A




Fig. 23B




Fig. 23C

Collision Detected

2025 RELEASE UNDER E.O. 14176




Fig.24




Fig. 25






Fig.26






Fig. 29

Fig. 30





Fig. 31

Circuit Information
⏏

Facility

Bay:

Shelf:

Circuit:

CILI:

Patch: ☐

Equipment

⌚

Bay:

Shelf:

Circuit:

CILI:

Patch: ☐

Fig.32




Fig.33




Fig.34

DSXP

ERT

X-CONN

INFO SCREEN

FACILITY

Central Office: Malibu

Floor: Main

Bay: 1

Panel: 6

Circuit: 64

CLLI: MALTOLL10

STATUS: Connected

EQUIPMENT

Central Office: Malibu

Floor: Main

Bay: 1

Panel: 7

Circuit: 18

CLLI: Fiber-route1

STATUS: Connected

GENERAL INFORMATION

Install Date: 11/10/97

Last Patch Date: 11/12/97

Last Patch Location: Bay1-PNL2-CCT12

Last Patch CLLI: Fiber-route4

Priority: 1

Emergency Patch Location: Bay2-PNL3-CCT20

Comments: Malibu Toll Route

Fig. 35

DSXPRT X-CONN INFO SCREEN

FACILITY

Central Office: Malibu
 Floor: Main
 Bay: 1
 Panel: 6
 Circuit: 64
 CLLI: MALTOLL10
 STATUS: *PATCHED*

EQUIPMENT

Central Office: Malibu
 Floor: Main
 Bay: 1
 Panel: 7
 Circuit: 18
 CLLI: Fiber-route1
 STATUS: Connected

PATCHED

Central Office: Malibu
 Floor: Main
 Bay: 2
 Panel: 2
 Circuit: 6
 CLLI: Fiber-route2
 STATUS: *PATCHED*

Fig. 36